N123		AIRWORTHINESS LIMITATIONS ANNUAL Inspection				AIRCRAFT	
	Manufacturer	PN or Model & (Year)	Serial Number	TCDS + Rev		TTSN	TSOH
Aircraft	PIPER	PA32R-301(HP) (1997)	3246060	A3SO Rev.33		1969:12'	NA
Engine	LYCOMING	IO-540-K1G5	L-25921-48A	1E4 Rev.25		1969:12'	NA
Propeller	HARTZELL	HC-I3YR-1RF/	HK127A	P33EA Rev.23		1969:12'	1247:18'
.Blades	PN: F7663DR	SN.1: H94377 SN.2: H94380 SN.3: H94382				TACH:	Counter:
Comments & Notes:	Total TIMES based Last Propeller over	1969:2/10'	2118:8/10'				

REGISTERED OWNER: OPERATOR:

AXIS AIRCRAFT LEASING INC TRUSTEE 2711 CENTERVILLE RD STE 400 WILMINGTON, DELAWARE 19808-1645 UNITED STATES Mr. Didier Borremans

- Annual/100 Hrs Inspection performed on this aircraft, including Airframe, Engine and Propeller IAW FAR43. App.D.
- Recommended Inspections, lubrications and servicing performed IAW Piper, Lycoming & Hartzell Service Manuals.
- AD's Checked up to **Biweekly 2017-13**. Run-ups performed and operations found satisfactory and within limits.

AIRWORTHINESS LIMITATIONS & AD compliances	Model / PN	SN	LIMIT interval	Last performed	Next Due
Registration expiration date:	N123AX		-	NOV-20-2008	NOV/2018
Radio Station License expiration date:	N123AX		-	FEB-02-2010	MAR/2020
Annual-100.Hrs Inspection required by FAR91.409 and IAW FAR43.App D.	NA	NA	100.Hrs 12.Month	1969.Hrs JUN-30-2017	2069.Hrs JUN-2018
ELT Inspection + test IAW FAR91.207(d)	AmeriKing AK-451-21	5497	12.Month	1969.Hrs JUN-30-2017	JUN-2018
ELT Batteries – main unit - replacement	AmeriKing 4500010-1	NA	5.Yrs	MAY-2015	MAY/2020
ELT Batteries – remote panel - replacement	DURACELL DL1/3 NB	NA	5.Yrs	MAY-2015	MAY/2020
Transponder test required by FAR91.413 Per FAR43.App.F	KT73 066-01164-0101	4267 F23742	24.Month	MAR-31-2016 By Lambert	MAR/2018
Altitude Encoder test required by FAR91.411 Per FAR43.App.E	ACK A-30	79116	24.Month	MAR-31-2016 By Lambert	MAR/2018
Altimeter #1-ASPEN 1000- Test required by FAR91.411 Per FAR43.App.E	EFD1000 910-00001-001	22660	24.Month	MAR-31-2016 By Lambert	MAR/2018
Altimeter #1-Standby- Test required by FAR91.411 Per FAR43.App.E	UI 5934PD-3	389282	24.Month	MAR-31-2016 By Lambert	MAR/2018
Altimeter #2 –test required by FAR91.411 Per FAR43.App.E	UI 5934PD-3	389011	24.Month	MAR-31-2016 By Lambert	MAR/2018
VOR equipment test IAW FAR91.171 For IFR operations			30.Days	MAR-31-2016 By Lambert	DUE
FAA-AD *2015-19-07 EFF.NOV/03/2015 LYCOMING Fuel injector fuel lines inspected IAW SB342G.	IO-540-K1G5	L-25921-48A	100.Hrs	1969.Hrs JUN-30-2017	2069.Hrs
FAA-AD*2013-02-13 EFF.MAR/11/2013 Piper: Stabilizer Control Systems: Inspect IAW SB1245			2000.Hrs 7.Yrs	1554.Hrs DEC-02-2013	3554.Hrs DEC-2020
FAA-AD*2004-10-14 EFF.JUN/25/2004 Lycoming Crankshaft gear bolt - Replacement at prop strike	IO-540-K1G5	L-25921-48A	Prop Strike	1452.Hrs NOV-14-2012	Prop strike
FAA-AD*99-04-04 EFF.FEB/25/1999 Lycoming Slick magneto Impulse coupling inspection	6351	08020428	250.Hrs	1969.Hrs JUN-30-2017	2219.Hrs
Recommended Magneto 500.Hrs inspection	LH: 6351 RH: 6350	08020428 07111491	500.Hrs 500.Hrs	1969.Hrs 1969.Hrs	2469.Hrs 2469.Hrs
Recommended next 50.Hrs inspection			50.Hrs	1969.Hrs	2019.Hrs

"I certify that this Aircraft – including Airframe, Engine and Propeller - has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition."

Date: JUN-30-2017.

Signed: Luc Van de Maele - A&P2325348-IA

TTSN = Total Time Since New
Abbreviations used: TSOH = Time Since Overhaul
IAW = In Accordance With

\* = Recurring AD
TT = Total Time

NA = Not Applicable CW = Complied With PCW= Previously Complied With