Aircraft Regis Aircraft Engine	Manufacturer		_ mspec	tion			AIII	RAFT	APR-26-201 Page 1 of 1
Engine		PN or Model & (Yea		Serial I	Number	TCD	S + Rev	TTSN	тѕон
-	PIPER	PA32R-301(HP) (6060		D Rev.33	2067:00'	NA
	LYCOMING	IO-540-K1G5			21-48A		Rev.26	2067:00'	NA
Propeller	HARTZELL	HC-I3YR-1RF			27A		A Rev.23	2067:00'	1345:06'
.Blades	PN: F7663DR	SN.1: H94377 SN.1	2: H9438	30 S	N.3: H943	882		TACH:	Counter:
Comments & Notes:		ed on TACH-METER read erhaul @ 721:9/10 Prop 1		ach) on O	CT-17-200)2		2067:0/10'	2226:9/10
REGISTERED OWNER:				OPERATOR:					
AXIS AIRCRAFT LEASING INC TRUSTEE 2711 CENTERVILLE RD STE 400 WILMINGTON, DELAWARE 19808-1645 UNITED STATES				Mr. Didier Borremans					
- Recomm	nended Inspectio	on performed on this ai ons, lubrications and se eekly 2018-08. Run-u	ervicing	performe	ed IAW Pi	per, Lyc	oming & Ha	artzell Service	e Manuals.
AIRWORTHINESS LIMITATIONS & AD compliances			Model / PN SN		SN		LIMIT interval	Last performed	Next Due
Registratio	on expiration date:		N123AX				-	NOV-20-200	8 NOV-2018
Radio Station License expiration date:			N123AX					FEB-02-2010	MAR-202
Annual-100.Hrs Inspection required by FAR91.409 and IAW FAR43.App D.			NA		NA	NA		2067.Hrs APR-26-2018	2167.Hrs 8 APR-2019
ELT Inspection + test IAW FAR91.207(d) CW OK + FAA-AD *2017-16-01 EFF.OCT/24/2017 : CW			AmeriKing AK-451-21		5497	5497		2067.Hrs APR-26-2018	APR-201
ELT Batteries – main unit - replacement			AmeriKing 4500010-1		NA	NA		MAY-2015	MAY-202
ELT Batteries – remote panel - replacement			DURACELL DL1/3 NB		NA	NA		MAY-2015	MAY/202
Transponder test required by FAR91.413 Per FAR43.App.F			KT73 066-01164-0101		4267 F23742		24.Month	JAN-31-2018 By Lambert	
Altitude Encoder test required by FAR91.411 Per FAR43.App.E			ACK A-30		79116	79116		JAN-31-2018 By Lambert	
Altimeter #1-ASPEN 1000- Test required by FAR91.411 Per FAR43.App.E			EFD1000 910-00001-001		22660	22660		JAN-31-2018 By Lambert	
Altimeter #1-Standby- Test required by FAR91.411 Per FAR43.App.E			UI 5934PD-3		389282	389282		JAN-31-2018 By Lambert	
	timeter #2 -test required by FAR91.411 Per FAR43.App.E		UI 5934PD-3		389011	389011		JAN-31-2018 By Lambert	
	OR equipment test IAW FAR91.171 For IFR operations							UNKNOWN	DUE
FAA-AD *2015-19-07 EFF.NOV/03/2015 LYCOMING Fuel injector fuel lines inspected IAW SB342G.		IO-540-K1G5		L-25921	-48A	100.Hrs	2067.Hrs APR-26-2018	2167.Hr s	
FAA-AD*2013-02-13 EFF.MAR/11/2013 Piper: Stabilizer Control Systems: Inspect IAW SB1245							2000.Hrs 7.Yrs	1554.Hrs DEC-02-2013	3554.Hrs 3 DEC-202
FAA-AD*2004-10-14 EFF.JUN/25/2004 Lycoming Crankshaft gear bolt - Replacement at prop strike			IO-540-K1G5		L-25921	L-25921-48A		1452.Hrs NOV-14-2012	2 Prop 2 strike
FAA-AD*99-04-04 EFF.FEB/25/1999 Lycoming Slick magneto Impulse coupling inspection			6351		0802042	08020428		1969.Hrs JUN-30-2017	2219.Hr s
Recommended Magneto 500.Hrs inspection			LH: 6351 RH: 6350			08020428 07111491		1969.Hrs 1969.Hrs	2469.Hrs 2469.Hrs
Recommended next 50.Hrs inspection							50.Hrs	2067.Hrs	2117.Hrs
in Annual Date: APR	l inspection and R-26-2018.	ft – including Airfran d was determined to le – A&P2325348-IA					been inspe	ected in acco	ordance wi

Abbreviations used:	TTSN = Total Time Since New TSOH = Time Since Overhaul	* = Recurring AD TT = Total Time	NA = Not Applicable CW = Complied With				
	IAW = In Accordance With	TCDS = Type Certificate Data Sheet	PCW= Previously Complied With				
==== KEEP ON BOARD AT ALL TIMES ====							