N123A		AIRWORTHINESS LIMITATIONS ANNUAL Inspection						Date: APR-28-2022 Page 1 of 1	
	Manufacturer	rer PN or Model & (Year)		Serial Number TO		DS	TTSN	TSOH	
Aircraft	PIPER	PA32R-301(HP) (1997)	324	6060	A3	SO	2411.2/10'	NA	
Engine	LYCOMING	IO-540-K1G5	L-2592	L-25921-48A		E4	2411.2/10'	211.2/10'	
Propeller	HARTZELL	HC-I3YR-1RF/	HK1	127A	P3	3EA	2411.2/10'	1689.3/10'	
Blades	PN: F7663DR	SN.1: H94377 SN.2	: H94380	SN.3: F	194382		TACH:	Counter HOBBS	
Comments & Notes:	- Engine overhaul	sed on TACH-METER reading ed @2200:0/10' Engine TTSN auled @721:9/10' Prop TTSN (2411.2/10'	2603.0/10'					

REGISTERED OWNER: OPERATOR:

AXIS AIRCRAFT LEASING INC TRUSTEE 251 LITTLE FALLS DR

WILMINGTON DELAWARE 19808-1674

UNITED STATES

Mr. Didier Borremans

- Annual/100 Hrs Inspection performed on this aircraft, including Airframe, Engine and Propeller IAW FAR43. App.D.
- Recommended Inspections, lubrications and servicing performed IAW Piper, Lycoming & Hartzell Service Manuals.
- Filters-oil, fuel and air removed, inspected & cleaned: No Remarks. New Filter air BA-3 installed.
- Engine oil drained, inspected & serviced with 11 Qts W100. New Filter Oil PN AA48110-2 installed.
- FAA-AD 2022-03-15 (3/21/2022) Fuel Quantity Indicator GARMIN G3x GI275: Inspected: NA -PARTS NOT INSTALLED.
- AD's Checked up to Biweekly 2022-08. Run-ups performed and operations found satisfactory and within limits.

Differential cylinder Leak check: /80.PSI Cyl.		1: 75 Cyl.2: 72		2 Cyl.3: 75	Cyl.4: 76	Cyl.5: 75	С	Cyl.6: 78	
AIRWORTHINESS LIMITATIONS & Recurring AD compliances			/ PN	SN	LIMIT interval	Last performed		Next Due	
Registration expiration date:			(-	NOV-20-2008		OCT-2024	
Radio Station License expiration date:			(10.Yrs	APR-18-2020		APR-2030	
Annual-100.Hrs Inspection required by FAR91.409 and IAW FAR43.App D.			(100.Hrs 12.Month	2411.Hrs APR-28-2022		2511.Hrs APR-2023	
ELT Inspection + test IAW FAR91.207 (d) CW: Inspected & tested OK.			1000	251-15488	12.Month	2411.Hrs APR-28-2022		APR-2023	
ELT Batteries – main unit - replacement			4-1	NA	6.Yrs	NEW JUL-2019		DEC-2025	
ELT Batteries – remote panel - replacement				NA	NA	NA		NA	
Transponder test required by FAR91.413 Per FAR43.App.F			64-0101	4267 F23742	24.Month	APR-2022 By Lambert		APR-2024	
Altitude Encoder test required by FAR91.411 Per FAR43.App.E				79116	24.Month	APR-2022 By Lambert		APR-2024	
, , ,)0)01-001	22660	24.Month	APR-2022 By Lambert		APR-2024	
Altimeter #1-Standby- Test required by FAR91.411 Per FAR43.App.E)-3	389282	24.Month	APR-2022 By Lambert		APR-2024	
Altimeter #2 - Test required by FAR91.411 Per FAR43.App.E)-3	389011	24.Month	4.Month APR-2022 By Lambert		APR-2024	
VOR equipment test IAW FAR91.171 For IFR operations using VOR.					30.Days	UNKNOWN		DUE	
FAA-AD*2015-19-07 Lycoming: Fuel injector lines: Inspected IAW SB342G: OK			K1G5	L-25921-48A	100.Hrs	0.Hrs 2411.Hrs APR-28-2022		2511.Hrs	
FAA-AD*2013-02-13 Piper: Stabilizer Control Systems: Inspected IAW SB1245:OK					2000.Hrs 7.Yrs			4324.Hrs APR-2028	
FAA-AD*2004-10-14 Lycoming: Crankshaft gear bolt: Replaced during engine OH.			K1G5	L-25921-48A	Prop Strike			In case of Prop-strike	
FAA-AD*99-04-04 Lycoming: Slick magneto Impulse Coupling: Inspected: OK.				19020425	250.Hrs	Hrs 2411.Hrs APR-28-2022		2661.Hrs	
			51 50	19020425 19030842	500.Hrs 500.Hrs	2200.Hrs 2200.Hrs		2700.Hrs 2700.Hrs	
Recommended next 50.Hrs inspection	Recommended next 50.Hrs inspection				50.Hrs	2411.Hrs	3	2461.Hrs	

"I certify that this Aircraft has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition."

Date: APR-28-2022.

Signed: Luc Van de Maele – A&P2325348-IA

TTSN = Total Time Since New TSOH = Time Since Overhaul Abbreviations used:

IAW = In Accordance With

= Recurring AD TT = Total Time

NA = Not Applicable CW = Complied With PCW= Previously Complied With